

INVOICE

WDI Inspection For: 7529 FM 2446 Franklin, Texas 77856 9032854065

bryanrosewell@gmail.com

Client: Chance Rosewell

Report Number: 262980997

Invoice Date: Monday, November 30, 2020

Total Amount Due

\$189.44

Quar	ntity Description	Unit Price	Amount
1	Base Amount	\$175.00	\$175.00
1	Tax (8.25%)	\$14.44	\$14.44
		Subtotal:	\$189.44

Pay Now

Amount Due

\$189.44

Wellborn, TX 77881



Birds, Bats & Wood Destroying Insects



Texas WDI Report For: 7529 FM 2446, Franklin, TX 77856 Prepared Exclusively For: Chance Rosewell Inspected On: Monday, November 30, 2020

COPYRIGHT NOTICE

This report is the sole property of Randy Lee Inspections, LLC, and is protected material under the copyright laws of the United States of America. No copying, sale, or other unauthorized use of this report shall be permitted without the express, written consent of Randy Lee Inspections, LLC. Further, this report is valid only on the date of the report, and is for the sole use of the persons or entities named to whom the report is addressed. No sale, transfer, or other use of this report shall be permitted. No warranty or assurance is made by Randy Lee Inspections, LLC that wood destroying insects will not enter, infest, or become visible in the property after the date of the report.

Copied To: receptionist@aggielandtitle.com abbiewalshrealtor@gmail.com bryanrosewell@gmail.com appointments@randyleeinspections.com

Randy Lee Inspections, LLC, PO Box 456 Wellborn, TX 77881

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

7529 FM 2446	Franklin	77856		
Inspected Address	City	Zip Code		

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
- F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.
- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended.
 Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure,
 (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

SPCS/T-5 (Rev. 9/1/2019) Page 3 of 8

7529 FM 2446		<u>Fra</u>	anklin							<u>778</u>	56	
Inspected Address			City							Zi	p Code	
1A. Randy Lee Inspectio	ns, LL(C		_{1B.} 073	3191 ⁻	1						
Name of Inspection Comp							SPCS Busi	iness Lice	nse Num	ber		
_{1C.} PO Box 456 Wellbor	n,TX 7	7881								(9	979) 690	-6775
Address of Inspection Cor				City			State		Zip	`	Telephone	e No.
_{1D.} Randy Lee					1.E		Certified Ap	nnlicator		X	(check on	e)
Name of Inspector (Please	e Print)				_'		Technician				(GIICON OII	C)
				₄- Mor	ndav.	. No	vembei	r 30. 2	020			
				Inspection		,						_
2. Chance Rosewell					Selle	r 🗆 A	Agent 🗌 E	Buyer 🛚	Manage	ment Co. 🔲	Other	
Name of Person Purchasi	ng Inspecti	ion										
3. Owner/Seller					_							
4.REPORT FORWARDED TO: Titl (Under the Structural Pest							Seller receive a c	copy)	Agent	X	Buyer 🛚	
								177				
The structure(s) listed below were ins This report is made subject to the con											Structural Pes	Control Service
•								g				
5A. Home List structure(s) inspected that may in	clude resid	dence detached gara	uges and oth	ner etructur	es on tl	he nroi	nerty (Ref	or to Part	A Scone	of Inspection	<u>, , , , , , , , , , , , , , , , , , , </u>	_
	ciude resid	dence, detached gara	iges and on	iei structur	es on u	ne pro	perty. (IXer	ei io raii	А, Эсоре	or mspection	')	
5B. Type of Construction: Foundation: Slab 🗵 Pier & Bear	m □ Pier ·	Туре:	Base	ement 🔲 (Other: _							
Siding: Wood ☐ Hardie Plank Roof: Composition ☐ Wood	t 🔲 Brick [🔲 Stone 🗶 Stucco 🛭	Other:									
·												
6A.This company has treated or is tre If treating for subterranean termites, the	he treatme	nt was:	Partial		Spot			Bait		Other		_
If treating for drywood termites or rela	ted insects	s, the treatment was:	Full		Limite	ed						
6B			_					_				
Date of Treatment by Insp	ecting Cor	mpany		Comm	non Nar	ne of l	nsect		Nan	ne of Pesticide	e, Bait or Othe	er Method
This company has a contract or warra	inty in effec	ct for control of the fo	llowing woo	d destroyin	ng insed	cts:						
Yes □ No	_											
If "Yes", copy(ies) of wa	rranty and	treatment diagram	must be a	ttacned.								
Neither I nor the company for which I I nor the company for which I am actir								purchase	or sale o	of this property	y. I do further	state that neithe
Signatures: Randy Z.		0560526										
Inspector (Technician or Certified A	pplicator N	Name and License Nu	ımber)	_								
Others Present:												
7B					_							
Apprentices, Technicians, or Certific	ed Applicat	tors Name(s) and Reg	gistration/Li	cense Num	nber(s)							
Notice of Inspection Was Posted At or	r Near:											
8A. Electric Breaker Box		8B. I	Date Posted	d: <u>11/30/2</u>	20							
Water Heater Closet Beneath the Kitchen Sink												
9A.Were any areas of the property ob (Refer to Part B & C, Scope of Inspec				Yes	X			No				
9B.The obstructed or inaccessible are							_				_	
Attic Deck		nsulated area of attic sub Floors		Plumbing Slab Joint			X X	Planter b		ng structure		
Soil Grade Too High		leavy Foliage	X	Eaves			X	Weephol			_	
Other 10A.Conditions conducive to wood de (Refer to Part J, Scope of Inspection)	estroying in			Yes	X			No				
10B.Conducive Conditions include bu	t are not lir	mited to:										
Debris under or around structure (K)	X	Wood to Ground Co		high (I \			ooards left i Rot (M)	in place (I)	Excessive M Heavy Folia		□ x
Planter box abutting structure (O)		Wood Pile in Conta						n Contact	with the	Structure (R)		
Insufficient ventilation (T)		Other (C)	Specify:	_								
		Licensed and	l Regulater	d by the Te	exas Da	epartm	ent of Aar	riculture				
	P	O Box 12847, Austir							32-2567			

7529	FM 2446			F	ranklin			778	356
Inspected Address 11. Inspection Reveals Vis 11A.Subterranean Termite 11B.Drywood Termites 11C Formosan Termites 11D.Carpenter Ants 11E .Other Wood Destroyin	s	n or on the struct	City ure:	Active Infe	estation No 🔀 No 🛣 No 🛣 No 🛣 No 🛣	Prev Yes Yes Yes Yes Yes	□ No X □ No X □ No X	Yes [Yes [Yes [Yes [□ No 🖬
Specify:	•	, ,,	esticides, baits, exist	ting treatme	nt stickers or otl	ner methods) i	dentified:		
11G.Visible evidence of:				has been	observed in the	following area	as:		
If there is visible evidence inspected must be noted in 12A. Corrective treatment Scope of Inspection) 12B. A preventive treatmer Specify reason: Refer to Scope of Inspe	the second bla recommended nt and/or correc	nk. (Refer to Par for active infesta	t D, E & F, Scope of tion or evidence of p Yes	Inspection) previous infe	station with no	prior treatmer	nt as identified i	in Section 11. (Refer t	
Troid to doops of mope	olion i dit o		Diagram (of Structi	ure(s) Inspe	ected			
The inspector must draw a Evidence of Infestation, A-, Carpenter Ants; Other(s) –	Active: P-Previo	ous; D-Drywood 7	perimeter measurem Fermites; S-Subterra	ents and inc	dicate active or	previous infest	tation and type Conducive Cond	of insect by using the fo ditions; B-Wood Boring	illowing codes: E- Beetles; H-
					29 FM 24				
				FA	esuklin, Tx	11856			
				í			7		
				1	Pa	ROH	K		
				3	Sep.	5/AB _	-KK-		
	ì		Ponc	H 6	6'		Popul	H K	
		CAR	w Tility		Room	1	Bco 11	91 Z 3.1	
		51	KITCHEN B					K	
			ם ו	שווא		STAIRS	Bed		
						ENTH		PORCH I	
			Sovery						
Additional Comments W	DI 2015								

7529 FM 2446	Franklin	77856			
Inspected Address	City	Zip Code			
	Statement of Purchaser				
		I have also read and understand the "Scope of Inspection."			
If additional information is attached, list number of pages: 5 Signature of Purchaser of Property or their Designee	Date	-			
	Buyer's Initials				
SPCS/T-5 (Rev. 9/1/2019)		Page 6 of 8			

Page 6 of 8

Inspection Summary From Your Inspector

INSPECTION SUMMARY

Thank You Chance and Abbie Walsh,

During my visual inspection today, I did not see any visible signs of active wood destroying insects.

GENERAL PEST CONTROL

The best time to do a general pest control treatment is when the home is empty.

Best Regards, Randy Lee

Photos

SECTION 10A - CONDUCIVE CONDITIONS



K. Debris on roof & gutters



K. Debris on roof & gutters



L. Ground High on slab



N. Heavy folige

GRAPH GUIDE

Conducive Conditions

G=Wood To Ground Contact

Increases the Chance of: Termites, Fire Ants, Wood Rot, and all other Ants.

Remedies: Correct all Wood to Ground Contact, no Siding or wood trim in contact with the ground.

I=Form boards left in Place

Increases the Chance of: Termites, Carpenter Ants, Fire Ants.

Remedies: Remove when they rot out and replace with caulk or sand.

J=Excessive Moisture

Increases the Chance of: Termites, Carpenter Ants, and all other Insects.

Remedies: Fix all leaks; correct all standing water around home, All water and gutters should drain away from the slab.

K=Debris Under or Around Structure

Increases the Chance of: Termites, Carpenter Ants, Harbors all insects, Wood Rot, Wood Boring Beetles, Carpenter Bees.

Remedies: Keep all debris away from the home. Bricks, Stored wood, leaves & Compost, Keep Gutters & Roof clean of leaves & limbs.

L=Footing too Low or Soil Line too High

Increases the Chance of: Termites, Fire Ants, Moisture Damage.

Remidies: Try to keep a minimum of 2 to 4 inches of slab exposure around the home.

M=Wood Rot

Increases the Chance of: Termites, Carpenter Ants, Carpenter Bees, Wood Boring Beetles, all other Insects.

Remedies: Replace all wood rot, caulk and seal, keep all exterior wood painted and sealed.

MS=Moisture Stains

Increases the Chance of: Termites, Carpenter Ants, all other insects.

Remidies: Need to have checked to make sure there is still not an active leak.

N=Heavy Foliage

Increases the Chance of: Carpenter Ants, Spiders, Wood Rot.

Remedies: Keep all tree limbs trimmed back 4 foot from structure. Keep all shrubs, vines, and crepe myrtles 18 inches to 2 foot off the

structure

O=Planter Box Abutting Structure

Increases the Chance of: Termites, Carpenter Ants, Fire Ants, Moisture Damage.

Remedies: Remove the Planter Box, or remove all the soil from the Planter Box and seal try not to put soil back in to the Planter Box.

Make sure Planter Box has holes at the bottom to drain water away from the structure.

Q=Wood Pile in Contact with Structure

Increases the Chance of: Termites, Wood Boring Beetles, Carpenter Ants, Harbors other Insects.

Remedies: Keep all wood off the ground and as far away from the structure as possible.

R=Wooden Fence in Contact with Structure:

Increases the Chance of: Termites, Carpenter Ants, Crawling Insects.

Remedies: Keep fence off structure. Try not to connect fence to the structure.

T=Insufficient Ventilation

Increases the Chance of: Termites, Wood Rot, Decay, Mold, Mildew, and all other Insects.

Remedies: Install or Increase the number of vents in the crawl space, Install a moisture barrier or moisture fans. Use sump pumps to keep water from standing under the structure.