


COLLAR DETAIL

POST HYDRANT ASSEMBLY

- 1. EXISTING 2" DIA. 100' W.P. HYDRANT
- 2. NEW 2" DIA. 100' W.P. HYDRANT
- 3. NEW 2" DIA. 100' W.P. HYDRANT
- 4. NEW 2" DIA. 100' W.P. HYDRANT
- 5. NEW 2" DIA. 100' W.P. HYDRANT



NOTE:
 ALL EXISTING EQUIPMENT INFORMATION AND READINGS
 AT LATEST HAS TAKEN FROM A FIELD SURVEY BY
 TYSON CONSULTING SUBDIVISION PREPARED BY
 STEVE, DATED MAY 21, 1985.

9-8-85
 SUBDIVISION REGULATIONS
 DO NOT APPLY
 (See Subdivision Plat)

DATE	BY	REVISION
9-8-85	STB	1
1-14-86	STB	2
1-14-86	STB	3
1-14-86	STB	4
1-14-86	STB	5



ES&T
 ENVIRONMENTAL TECHNICAL
 P.O. BOX 1887
 CHURCH RD
 LENOIR, NC 28772-18

TYSON C
 SUBDIVISION
 AS - I
 WATER DISTRIBUTION SYSTEM

PREPARED BY
 STEVE
 SC

PROJECT NO.
 225-88608

