

Water Quality: **Strata Depth (ft.)** 90 **Water Type** good (800 ppmTDS)
 Chemical Analysis Made: **No**
 Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**
 111 E. Grayson St.
 Llano, TX 78643

Driller Name: **Taylor Virdell Jr.** **License Number:** 1900

Comments: **No Data**

Lithology:			Casing:			
DESCRIPTION & COLOR OF FORMATION MATERIAL			BLANK PIPE & WELL SCREEN DATA			
Top (ft.)	Bottom (ft.)	Description	Dia. (in.)	New/Used	Type	Setting From/To (ft.)
0	1	Topsoil	6"	N	PVC +2	64 sch 40
1	63	Broken Red & Black Metamorphic				
63	100	Red & Black Metamorphic				

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
 P.O. Box 12157
 Austin, TX 78711
 (512) 334-5540