

# STATE OF TEXAS WELL REPORT for Tracking #476302

Owner: **Lee Porter** Owner Well #: **1**  
Address: **1062 Tahoe Road** Grid #: **56-45-5**  
**Harper, TX 78631**  
Well Location: **From Hwy 290 turn left on Co Rd 442** Latitude: **30° 19' 00.04" N**  
**go 1.6 miles to Tahoe Rd to the left go** Longitude: **099° 27' 18.1" W**  
**through Tahoe Gate then turn left to** Elevation: **2217 ft. above sea level**  
**Lot 3 well is .03 miles.**  
**Junction, Texas, TX 76849**  
Well County: **Kimble**

Type of Work: **New Well** Proposed Use: **Domestic**

Drilling Start Date: **3/6/2018** Drilling End Date: **3/7/2018**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	<b>8</b>	<b>0</b>	<b>310</b>

Drilling Method: **Air Rotary**

Borehole Completion: **Straight Wall**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks &amp; material)</i>
Annular Seal Data:	<b>0</b>	<b>5</b>	<b>Cement 3 Bags/Sacks</b>
	<b>5</b>	<b>20</b>	<b>Bentonite 4 Bags/Sacks</b>

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **100**

Distance to Septic Field or other concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed** **Surface Completion by Driller**

Water Level: **No Data**

Packers: **No Data**

Type of Pump: **Submersible**

Well Tests: **Yield: 10 GPM**

Water Quality:	<i>Strata Depth (ft.)</i>	<i>Water Type</i>
	<b>240 - 310</b>	<b>good water</b>

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Allison Well Service**  
**191 Allison Road**  
**Junction, TX 76849**

Driller Name: **Robert M. Allison** License Number: **54624**

Apprentice Name: **William D Allison** Apprentice Number: **57293**

Comments: **good water**

Lithology:  
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:  
BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
<b>0</b>	<b>4</b>	<b>top soil</b>
<b>4</b>	<b>20</b>	<b>yellow limestone</b>
<b>20</b>	<b>50</b>	<b>white limestone</b>
<b>50</b>	<b>310</b>	<b>cave-no returns after cave</b>

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
<b>8.58</b>		<b>New Steel</b>		<b>-1</b>	<b>2</b>
<b>4.5</b>	<b>Blank</b>	<b>New Plastic (PVC)</b>		<b>-1</b>	<b>40</b>
<b>4.5</b>	<b>Perforated or Slotted</b>	<b>New Plastic (PVC)</b>		<b>40</b>	<b>270</b>

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation**  
**P.O. Box 12157**  
**Austin, TX 78711**  
**(512) 334-5540**