

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

KLAM 58894

WELL I.D. LABEL# L

110343

START CARD #

1022851

ORIGINAL LOG #

10/1/2014

(1) LAND OWNER

Owner Well I.D.
First Name JON Last Name ZBINDEN
Company ZBINDEN PROPERTIES, LLC.
Address 817 NE BROADWAY ST.
City PORTLAND State OR Zip 97232-1215

(2) TYPE OF WORK

[X] New Well [] Deepening [] Conversion
[] Alteration (complete 2a & 10) [] Abandonment (complete 5a)

(2a) PRE-ALTERATION

Dia + From To Gauge Stl Plstc Wld Thrd
Casing: [] [] [] [] [] [] [] []
Material From To Amt sacks/lbs
Seal: [] [] [] [] [] [] [] []

(3) DRILL METHOD

[X] Rotary Air [X] Rotary Mud [] Cable [] Auger [] Cable Mud
[] Reverse Rotary [] Other

(4) PROPOSED USE

[] Domestic [] Irrigation [] Community
[] Industrial/ Commercial [] Livestock [] Dewatering
[X] Thermal [] Injection [] Other

(5) BORE HOLE CONSTRUCTION

Depth of Completed Well 1148.00 ft. Special Standard [] (Attach copy)

Table with columns: Dia, From, To, Material, SEAL, From, To, Amt, lbs, sacks/

How was seal placed: Method [] A [] B [] C [] D [] E

[X] Other POURED DRY

Backfill placed from ___ ft. to ___ ft. Material

Filter pack from ___ ft. to ___ ft. Material Size

Explosives used: [] Yes Type Amount

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount Actual Amount

(6) CASING/LINER

Table with columns: Casing, Liner, Dia, +, From, To, Gauge, Stl, Plstc, Wld, Thrd

Shoe [] Inside [] Outside [] Other Location of shoe(s)

Temp casing [] Yes Dia From To

(7) PERFORATIONS/SCREENS

Perforations Method Holt down hole

Table with columns: Perf/ Screen, Casing/ Screen, Dia, From, To, Scrm/slot width, Slot length, # of slots, Tele/ pipe size

(8) WELL TESTS: Minimum testing time is 1 hour

[] Pump [] Bailer [X] Air [] Flowing Artesian

Table with columns: Yield gal/min, Drawdown, Drill stem/Pump depth, Duration (hr)

Temperature 98 °F Lab analysis [] Yes By

Water quality concerns? [] Yes (describe below) TDS amount

Table with columns: From, To, Description, Amount, Units

(9) LOCATION OF WELL (legal description)

County KLAMATH Twp 39.00 S N/S Range 9.00 E E/W WM
Sec 14 SE 1/4 of the SW 1/4 Tax Lot 500
Tax Map Number Lot
Lat ' " or DMS or DD
Long ' " or DMS or DD

[X] Street address of well [] Nearest address

4606 SOUTH SIDE EXPRESSWAY

(10) STATIC WATER LEVEL

Table with columns: Existing Well / Pre-Alteration, Date, SWL(psi), +, SWL(ft)

WATER BEARING ZONES Depth water was first found 110.00

Table with columns: SWL Date, From, To, Est Flow, SWL(psi), +, SWL(ft)

(11) WELL LOG

Ground Elevation

Table with columns: Material, From, To

Date Started 4/21/2014 Complete 9/1/2014

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number Date

Signed

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1844 Date 10/1/2014

Signed COLTER CHANCELLOR (E-filed)

Contact Info (optional) CHANCELLOR DRILLING & PUMP