

# EARTHSEARCH SOIL CONSULTING, LLC

---

2000 Mallory Ln.  
Suite 130-306  
Franklin, TN 37067  
(615) 210-5523

08 / 17 / 2021

To whom it may concern,

This letter is to verify that a preliminary soil evaluation was performed at 5313 Crown Rd. in Williamson Co. The soil on this tract was evaluated for subsurface sewage disposal possibilities. Some soil suitable for subsurface sewage disposal was located on the property. The soil was identified as the Humphreys series with an estimated absorption rate of 60-75 minutes per inch. Several areas of disturbance in the area of previous cultivation were seen in the newly flagged areas shown below, there is an undocumented field line for sewage disposal near the newly flagged area, there is a water line near the newly flagged area, and a utility line servicing the existing structure near the newly flagged area. Mapping will be required in order to determine the amount of suitable soil.

The approximate area is shown on the satellite image provided and is marked with orange pin flags onsite. **These findings are based on a preliminary evaluation only. Extra high intensity soil mapping, property line and easement locations will be required for final approvals. Only the Williamson County Department of Sewage Disposal has the authority to determine the number of bedrooms and system approvals.** For any questions please contact me at 615-210-5523.

Sincerely,

J. Michael Haarbauer



