STATE OF TEXAS WELL REPORT for Tracking #66051

Owner: Lawrence Doxsey Owner Well #: 2551

Address: **124 E. Rische** Grid #: **69-14-1**

San Antonio, TX 78204

Well Location: Mickel Creek RD. --- F.M. 2107

Medina, TX 78055 Longitude: 099° 21' 54" W

Well County: Bandera Elevation: 1726 ft. above sea level

Type of Work: New Well Proposed Use: Domestic

Drilling Start Date: 7/28/2005 Drilling End Date: 8/18/2005

 Diameter (in.)
 Top Depth (ft.)
 Bottom Depth (ft.)

 Borehole:
 12.25
 0
 55

 8
 55
 600

Drilling Method: Air Rotary

Borehole Completion: Straight Wall

Annular Seal Data:

Top Depth (ft.)

Bottom Depth (ft.)

Description (number of sacks & material)

1 Cement

2 280 15 Grout

Seal Method: **Pressure Grouting**Distance to Property Line (ft.): **50+**

Sealed By: Driller Distance to Septic Field or other

concentrated contamination (ft.): 100+

Distance to Septic Tank (ft.): No Data

Method of Verification: Measured

Surface Completion: Surface Slab Installed

Water Level: 224 ft. below land surface on 2005-08-08 Measurement Method: Unknown

Packers: 1 Rubber 280'

1 Rubber 300' 1 Rubber 510'

Type of Pump: Submersible Pump Depth (ft.): 360

Well Tests: Jetted Yield: 50 GPM

Water Quality:

Strata Depth (ft.)	Water Type
No Data	No Data

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which

contained injurious constituents?: Yes

Natural Injurious Constituents	Unnatural Injurious Constituents
Gypsum	

The driller did certify that while drilling, deepening or otherwise altering the above described well, injurious water or constituents was encountered and the landowner or person having the well drilled was informed that such well must be completed or plugged in such a manner as to avoid injury or pollution.

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the

driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in

the report(s) being returned for completion and resubmittal.

Company Information: Armadigger, Inc.

P.O. Box 1329 Bandera, TX 78003

Driller Name: Daniel Thaler License Number: 4404

Apprentice Name: Joe Alan Wiebush Apprentice Number: 1397

Comments: No Data

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing: BLANK PIPE & WELL SCREEN DATA

From (ft) To (ft) Description				
0 50 Gravel				
50 180 Brown & Grey L/S				
180 220 Brown & Grey Shale				
220 240 GYP & Brown L/S				
240 280 Brown & Grey L/S				
280 430 Brown & L. Brown L/S With				
Dark Brown L/S (Water at 400)				
430 460 L. Brown L/S With Green & Red				
Sandy L/S (Water at 450)				
460 500 Green, Brown & Red Sand				
(Water at 490)				
500 520 Dark Grey Shale & L. Green &				
Brown L/S (Water at 520)				

Dia. (in.)	New/Used	Туре	Setting From/To (ft.)			
4 1/2 N SCH 40 PVC 0' to 600'						
Slotted 400' to 600'						
8 N Sch	40 PVC 0	' to 55'				

520 560 Brown Sand (Water at 530	
& 550)	
560 600 L. Brown & Sandy L/S With Some	
Dark Red Clay (Water at 510 &	
590)	

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540