

STATE OF TEXAS WELL REPORT for Tracking #97552

Owner: Larry Johnson	Owner Well #: No Data
Address: 1945 Country Club Est. Circle San Angelo, TX 76904	Grid #: 56-13-3
Well Location: 1.8 mi. N of 29 on FM 1222; .2 mi. W in pasture TX	Latitude: 30° 51' 15" N
	Longitude: 099° 23' 24" W
Well County: Mason	Elevation: No Data

Type of Work: New Well	Proposed Use: Domestic
-------------------------------	-------------------------------

Drilling Start Date: **11/9/2006** Drilling End Date: **11/9/2006**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	9	0	116
	6.75	116	117
	6	117	420

Drilling Method: **Air Hammer**

Borehole Completion: **Open Hole**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	0	5	1 Cement
	5	30	4 Bentonite

Seal Method: **GROUT**

Sealed By: **Driller**

Distance to Property Line (ft.): **No Data**

Distance to Septic Field or other concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Pitless Adapter Used**

Water Level: **340 ft.** below land surface on **2006-11-09** Measurement Method: **Unknown**

Packers: **Rubber 30'**

Type of Pump: **Submersible** Pump Depth (ft.): **400**

Well Tests: **Jetted** Yield: **60+ GPM**

Water Quality:	<i>Strata Depth (ft.)</i>	<i>Water Type</i>
	340 - 420	good (590 ppmTDS)

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**
111 E. Grayson St.
Llano, TX 78643

Driller Name: **Taylor Virdell Jr.** License Number: **1900**

Apprentice Name: **James Caleb Virdell** Apprentice Number: **3254**

Comments: **No Data**

Lithology:
 DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
 BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	1	Topsoil
1	50	Brown Clay & Limestone
50	110	Gray Shale & Limestone w/Sand Streaks
110	210	Gray Sandy Limestone (Cap Mt.)
210	375	Red Sandstone (Hickory)
375	420	Gray Sandstone

<i>Dia. (in.)</i>	<i>New/Used</i>	<i>Type</i>	<i>Setting From/To (ft.)</i>
6"	N	PVC +2 - 117 sch 40	

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540