STATE OF TEXAS WELL REPORT for Tracking #328031				
Owner:	Joe Parish	Owner Well #:	1	
Address:	103 Reo Dr. Gatesville, TX 76528	Grid #:	41-32-2	
Well Location:		Latitude:	31° 35' 21" N	
	Parmila, TX	Longitude:	098° 02' 34" W	
Well County:	Hamilton	Elevation:	No Data	
Type of Work:	New Well	Proposed Use:	Domestic	

Drilling Start Date: 3/20/2013 Drilling End Date: 3/22/2013

	Diameter (in	.) Toj	o Depth (ft.)	Bottom Depth (ft.)	
Borehole:	12		0	80	
	6.75		80	580	
Drilling Method:	Air Rotary				
Borehole Completion:	Straight Wall				
	Top Depth (ft.) Bottom Depth (ft.)		D	Description (number of sacks & material)	
Annular Seal Data:	-2	5		3 cement	
	5	120		8 benseal	
Seal Method: Gr	avity feed		Distance to F	Property Line (ft.): 50+	
Sealed By: Driller Distance to Septic Field or other concentrated contamination (ft.): 100+					
			Distance to	Septic Tank (ft.): No Data	
			Metho	od of Verification: Measured	
Surface Completion:	Surface Sleeve I	nstalled			
Water Level:	405 ft. below lar	d surface on 2013	- 03-22 Mea	asurement Method: Unknown	
Packers:	Shale 460 Shale 440 Shale 420 Cement 120				
Type of Pump:	Submersible		Р	ump Depth (ft.): 480	
Well Tests:	Jetted	Yield: 30 GP	Μ		

	Strata Depth (ft.)	Water Type	_	
Water Quality:	460-580	Trinity		
		Chemical Analysis Made	: No	
	Did the driller	knowingly penetrate any strata which contained injurious constituents?		
Certification Data:	driller's direct supervi correct. The driller u	at the driller drilled this well (or the w ision) and that each and all of the sta nderstood that failure to complete the turned for completion and resubmitta	tements he required it	erein are true and
Certification Data: Company Information:	driller's direct supervi correct. The driller up the report(s) being re	ision) and that each and all of the stand nderstood that failure to complete the sturned for completion and resubmitta	tements he required it	erein are true and
	driller's direct supervi correct. The driller up the report(s) being re	ision) and that each and all of the stand nderstood that failure to complete the sturned for completion and resubmittan ter Well Service	tements he required it	erein are true and
	driller's direct supervi correct. The driller up the report(s) being re Tom Lovelace Wat 4997 Elm Grove Re	ision) and that each and all of the stand nderstood that failure to complete the sturned for completion and resubmittan ter Well Service d.	tements he required it	erein are true and

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	45	Overburden
45	65	Paloxy
65	300	Gray lime and shale
300	360	Water Sand, Tan, Green, Gray Shale
360	375	Dark Gray and Green Shale
375	420	Hard Tan and White lime Sandy lime
420	445	Red, Green Tan Sand Stone Shale
445	475	Red Shale Soft Red Green Sandy Shale
475	485	Water Sand
485	495	Red Shale
495	535	White Lime
535	555	Red, Green Sandy Shale
555	563	Gravel
563	580	Brown-Yellow Shale

Casing: BLANK PIPE & WELL SCREEN DATA

Dia. (in.)	New/Used	Туре	Setting From/To (ft.)			
4.5 New Plastic Solid +2-460						
4.5 New Plastic mf6 Screen 460-580 .032						

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540